

Job Role Name QP Code	Batch Name/Id	
Duration:	Max Marks:	80
Name of Candidate	Candidate Signature	
Assessor Name	Aadhaar Number	
Assessor Signature	Trainer Signature	
TP Name	TC Name	
TP/TC Stamp with Signature	Date	

Instruction:

- 1. All questions are compulsory
- The question papers consist of MCQ.
 You will be given 60 minutes
 Please read all questions carefully

- 5. There is no negative marking

TEL/N6400.Splice Optical Fiber

1.	Which process aligns two optical fiber cores for joining? A. Threading	3Marks
	B. Cabling	
	C. Crimping	
	D. Splicing	
2.	Which splice type uses electric arc to fuse fiber ends?	3Marks
	A. Clip joint	
	B. Mechanical splice	
	C. Ribbon tie	
	D. Fusion splice	
3.	Which tool prepares the fiber by removing coating?	3Marks
	A. Screwdriver	
	B. Fiber stripper	
	C. Cable tie	
	D. Hammer	
4.	What ensures minimum light loss at the splice point?	3Marks
	A. Extra heating	
	B. Thick coating	
	C. Loose fitting	
	D. Proper alignment	
5.	Which parameter indicates splice performance?	3Marks
	A. Jacket size	
	B. Tube count	
	C. Cable color	
	D. Splice loss	
6.	Which device measures splice loss in optical fibers?	3Marks
	A. Multimeter	
I D =		



	B. OTDR	
	C. Ohmmeter	
	D. Megger	
7.	What must be done before fusion splicing?	3Marks
	A. Clean fiber ends	
	B. Heat insulation	
	C. Add metal glue	
	D. Paint the fiber	
8.	What keeps fibers stable inside a mechanical splice?	3Marks
	A. Hot glue	
	B. Index-matching gel	
	C. Metal pin	
	D. Rubber wrap	
9.	Which step is necessary after completing a splice?	3Marks
	A. Protective sleeve heating	
	B. Spray coating	
	C. Metal welding	
	D. Cable hammering	
10	What is the primary cause of high splice loss?	3Marks
	A. Cable color	
	B. Loose clamps	
	C. Poor cleaving	
	D. Long jacket	
TEL	N6401.Test Effectiveness and Record Test Results	
	110401.1 CSt Effectiveness and record 1 CSt results	
	10401.1 est Effectiveness and Record 1 est Results	
-	Which tool is mainly used to check fiber link quality?	3Marks
-		3Marks
-	Which tool is mainly used to check fiber link quality?	3Marks
-	Which tool is mainly used to check fiber link quality? A. Cable cutter	3Marks
-	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper	3Marks
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun	3Marks
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR	
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing?	
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating	
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector	
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion	
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket	3Marks
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link?	3Marks
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code	3Marks
11	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation	3Marks
11 12 13	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation C. Jacket size D. Loop count	3Marks
11 12 13	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation C. Jacket size	3Marks
11 12 13	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation C. Jacket size D. Loop count What should be done before recording test results?	3Marks
11 12 13	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation C. Jacket size D. Loop count What should be done before recording test results? A. Remove cable ties	3Marks
11 12 13	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation C. Jacket size D. Loop count What should be done before recording test results? A. Remove cable ties B. Add gel coating	3Marks
11 12 13	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation C. Jacket size D. Loop count What should be done before recording test results? A. Remove cable ties B. Add gel coating C. Heat the splice	3Marks
11 12 13	Which tool is mainly used to check fiber link quality? A. Cable cutter B. Crimper C. Heat gun D. OTDR What does a high reflectance value indicate in fiber testing? A. Proper heating B. Dirty connector C. Strong jacket D. Good fusion Which parameter shows the total optical loss in a link? A. Color code B. Attenuation C. Jacket size D. Loop count What should be done before recording test results? A. Remove cable ties B. Add gel coating C. Heat the splice D. Clean connectors	3Marks 3Marks



		C. Test log	
		D. Packing sheet	
		2.1 mining shoot	
	16.	Which unit is commonly used to express fiber loss?	3Marks
		A. Newton	0 - 1 - 200 - 200
		B. Ampere	
		C. Decibel	
		D. Lumen	
	17	. What indicates a possible bend or break in OTDR trace?	3Marks
	17.	A. Sharp dip	01/101115
		B. Smooth line	
		C. Dark display	
		D. Thick spike	
	18	. Which document stores final verified measurement data?	3Marks
	10.	A. Work permit	Siviairs
		B. Safety chart	
		C. Test report	
		D. ID card list	
	10	. What improves accuracy during fiber testing?	3Marks
	1).	A. Use long cables	Siviairs
		B. Extra wrapping	
		C. Heavy sleeves	
		D. Clean test ports	
	20	. Why are test results recorded after splicing?	
	20.	A. Change color codes	
		B. Reduce cable weight	
		C. Track performance	
		D. Increase jacket size	
		D. HICICASC JACKET SIZE	
D	СТ	WSO/NO101 Employability Skills (20 Hours)	
יע		/VSQ/N0101.Employability Skills (30 Hours)	2Ml
	21.	Which skill helps a splicer communicate updates clearly to the team?	2Marks
		A. Color sorting	
		B. Active listening	
		C. Cable polishing	
	22	D. Line trenching	23/4 1
	22.	Which trait reflects professional behavior at a job site?	2Marks
		A. Timely reporting	
		B. Random shifting	
		C. Casual routing	
	22	D. Free roaming	234 1
	23.	Which digital tool is commonly used to share test reports?	2Marks
		A. Paint	
		B. Email	
		C. Calendar	
	2.4	D. Recorder	23/1
	<i>2</i> 4.	Which skill helps solve issues during fiber link testing?	2Marks
		A. Guesswork	
		B. Problem-solving	



- C. Cable wrapping
- D. Route tracing
- 25. Which quality builds trust with supervisors and clients? 2Marks
 - A. Integrity
 - B. Rough handling
 - C. Quick shifting
 - D. Fast roaming
- 26. Which document is required for employment verification? 2Marks
 - A. ID proof
 - B. Cable chart
 - C. Route sheet
 - D. Sleeve count
- 27. Which skill helps a splicer manage daily tasks efficiently? 2Marks
 - A. Free cabling
 - B. Random searching
 - C. Manual digging
 - D. Time management
- 28. Which habit improves workplace safety and teamwork? 2Marks
 - A. Silent working
 - B. Speedy walking
 - C. Clear communication
 - D. Extra roaming
- 29. Which attitude helps handle customer queries effectively? 2Marks
 - A. Polite response
 - B. Sharp reply
 - C. Quick escape
 - D. Loud reaction
- 30. Which skill is essential for adapting to new fiber technologies? 2Marks
 - A. Continuous learning
 - B. Extra tightening
 - C. Heavy lifting
 - D. Cable marking



Answer Key

1	D	11	D	21	В
2	D	12	В	22	Α
3	В	13	В	23	В
4	D	14	D	24	В
5	D	15	С	25	Α
6	В	16	С	26	Α
7	Α	17	Α	27	D
8	В	18	С	28	С
9	Α	19	D	29	Α
10	С	20	С	30	Α